GE Mining Industrea

BULLETIN 30064

MK4.5 MINECRUISER STEER AXLE



Prepared for:

Industry

Prepared by:

Ross Stutchbury



GE Industrea	Report No: 30064
--------------	------------------

1 GE Industrea

63 Bonville Avenue, Thornton

New South Wales 2322
PO Box 401 Beresfield

(ph) +61 2 40148500
(fax) +61 2 40148599

Title: Mk4.5 MineCruiser Steer Axle

Author: Ross Stutchbury

Client: GE Industrea

Client Contact: Ross Stutchbury

Client Reference:

Industrea Reference: 30064

Synopsis: This Bulletin advises steer axle failure hazard.

1.1 Revision / Checking History

REVISION NUMBER	DATE	CHECKED BY	ISSUED BY
Draft	8/11/2013		RCS

1.2 Distribution

DESTINATION	1.2.1.1 REVISION NUMBER									
	А	В	С	D	E	F	G	Н	ı	J
GE Industrea Library Sales	1									
Industry	1									

BULLETIN Mk4.5 Steer Axle

GE Industrea has been notified of front axle failures at the king pin joint that have caused the separation of the front wheel from the vehicle.





Mk 4.5 MineCruisers with ZF axles were manufactured up until 2008. This product is now approaching or has exceeded the end of design life. Arduous conditions in underground coal mines subject the vehicles to fatigue, corrosion, and general wear and tear.



GEI recommend that to continue operating the Mk4.5 vehicles, maintenance and inspection is required to ensure the vehicles remain sound. Inspection should include the disassembly of the steer axle to enable crack testing of the king pin joint and axle housings. GEI recommend that inspection should be made during suitable scheduled maintenance.



Communication: Spare part supply

The supplies of cast housings for the axle are no longer readily available from the OEM (Original Equipment Manufacturer) of the axle. Please contact GEI for current availability.

GE Industrea Thornton 02 40148500

GE Industrea Rutherford 02 40159000

GE Industrea Emerald 07 4982 0066

