

GE Mining
Industrea

BULLETIN 6723

PJB RED HEADLIGHT ASSEMBLY NON- CONFORMANCE



GE Mining
Industrea

ISSUED

7 JUN 2013

Prepared for: Industry

Prepared by: Ross Stutchbury



1 GE Industrea

63 Bonville Avenue, Thornton
 New South Wales 2322
 PO Box 401 Beresfield

Original Date of Issue: 7-06-2013

(ph) +61 2 40148500
 (fax) +61 2 40148599

Title: Mk7 MineCruiser Exhaust

Author: Ross Stutchbury

Client: GE Industrea

Client Contact: Ross Stutchbury

Client Reference:

Industrea Reference: 6723

Synopsis: This Bulletin advises individual recall for inspection of Red PJB Headlights.

1.1 Revision / Checking History

REVISION NUMBER	DATE	CHECKED BY		ISSUED BY	
A QLD	07.06.13			RCS	

1.2 Distribution

DESTINATION	1.2.1.1 REVISION NUMBER									
	A	B	C	D	E	F	G	H	I	J
GE Industrea Library	1									
Sales Industry	1									


BULLETIN PJB Headlight Fitting Non Compliance

GE Industrea has been notified of a non compliance issue with the assembly of the Red PJB Headlight M28300.



Communication: Non Conforming Assembly

The secondary lens (item 12) sits in front of the headlight globe inside the flameproof enclosure. Red lights have an 'Optional Colour Diffuser' (item 15) that sits behind the headlight enclosure's primary lens (item 3). Close inspection has found a batch of lights have been assembled with a red coloured secondary lens approximately 2.5mm thick, installed instead of a clear 4 mm glass.



Individual Recall: Headlight Inspection

GEI recommend that PJB Headlights be inspected to determine if the assembly of red lights are in compliance with the AUS Ex 983X Certificate of Conformity. Suitably qualified personnel are required to undertake the inspection in line with the requirements of AS3800.



Preparation: Red Lens

Please contact GE Industrea for supply of secondary lens (4mm clear toughened glass) and colour diffuser (red polycarbonate disc).

GE Industrea Thornton
02 40148500

GE Industrea Rutherford
02 40159000

GE Industrea Emerald
07 4982 0066

