

BULLETIN 31076

PJB ALTERNATOR EX LABEL



Date: 16/2/2015

Prepared for: Industry

Prepared by: Ross Stutchbury



GE Industrea Thornton
02 40148500

GE Industrea Rutherford
02 40159000

GE Industrea Emerald
07 4982 0066

BULLETIN Alternator Compliance Decal

GE Industrea advises the following information relating to the GE00058M-X Flame Proof Alternator.



Communication:


The Flame Proof Alternator GE00058M-X holding ANZEx 09.3007X certification has been released with incorrect labelling. The 'X' is missing from the compliance decal. The X indicates that specific **conditions of safe use** must be observed when the Alternator is installed.

Excerpt ANZEx 09.3007X

Conditions of Certification:

It is a condition of safe use that the installation of each alternator is carried out as follows:

- 1. In accordance with the manufacturer's Installation Notes*
- 2. Thermal insulation of the supply cable shall be at least rated for 100°C*



Label showing Certification number without X suffix.



Change/Action required:

GE Industrea recommends that all PJB Alternator labels be inspected at the next opportunity. Where the X is not included in the Certification number, an X should be stamped to permanently show the compliance requirement for *Conditions of Safe Use*. Each alternator application should review the installation and conditions of use to confirm compliance to the two conditions specified. Condition 1 – Installation Notes is attached for convenience.

Logistics: Please contact GE Industrea if further assistance is required.